25X1A

Approved For Release 2003/08/11 : CIA-RDP82-00457R003100200006-3 REPORT NO. CENTRAL INTEL GENCE AGENCY INFORMATION REPORT CD NO. DATE DISTR. 23 COUNTRY DISSE NO. OF PAGES The Lenin Works in Leningrad SUBJECT NO. OF ENCLS. PLACE 25X1A ACQUIRED 25X1 SUPPLEMENT TO DATE OF IN REPORT NO. THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE ACT 50 15, 5, C., 31 AND 32, AS AMENDED. ITS TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. REPRODUCTION OF THIS FORM IS PROHIBITED. THIS IS UNEVALUATED INFORMATION 25X1 SOURCE

> The Lenin Worker to assessed on the southwastern edge of Leningrad on the marks or the Neva giver, or possibly a branch of it. The distance between Side industrial concentration and the Moscow Railroad Station in Leadingrad is approximately four kilometers. One kilometer east of the factory in the direction of the city, the "F nnish Railroad" crosses the main highway. The fenced-in Lenin Works sit astride this main traffic artery leading mi of town.

the war and no new buildings lave been added since the war, but repairs wave been carried out steadil .

and engineers were never used professionally.

The factory is an old undertaling. Various buildings carry the dates of monstruction: 1900, 1904, 1900, 1908/10. No damage was inflicted during 25X1X

are specialists (Fachleute) in one field or another, recognized the teamwidel equipment as obsolete, wen though it is in some measure still efficient. large amounts of desintegrating German war booty machines, stacked for years in the broat factory yards, are going to waste. The entire gorks is extensively mechaniz d and cranes and crane carriages are available for the movement of heavy pie es in almost every branch or department. A new, mubile American crane on cate pillars, used for the loading of finished turnthough is reported to have a 1 fting capacity of 200 tons.

The plant management is heade by a civilian director who receives instructions direct from Moscow via a private line. This undertaking apparently was overldered sufficiently important to be inspected repeatedly by commissions. The composition of these commissions was partly civilian and partly military. Constrains were observed among nem. The advent of these ubiquitous inspectors considerable commotion among plant officials. On one occasion in 1940, the PMs were hustied out of t e workshops and plant yards on short notice. recommandly, FWs were not to be employed by the Lenin Works. Furthermore, German

Approved For Release 2003/08/11 CIA-RDP82-00457R003100200006-3												
STATE		NAVY		NSRB		DISTRIBUTION						
ARMY		AIR .		FBI								•

·	
Approved For Release 2003/08/11 : CTA-RDP82-00457R003100200006-3	

GENTRAL INTE LIGENCE EGENCY

. The most important insighinthing of the leads Vorko area

- 4. Mechanical workshops, assembly rooms, drafting rooms (second floor)
- 5. Buoy manufacturing plant (three buildings)
- o. Joiner's shop, pattern shop, sag mill
- 7. The power plant (turbines & boilers for current & steam)
- d. Administration and warehouses
- 3. Railroad track network and loco notive roundhouse
- J. Leningrad Camp # 7711 accommodated between 1200 and 1400 German PWs, some of whom worked at the Lenin Works and some at the "Bolshevik" Works. Several dozen Austrians passed through the camp in the spring of 1949. All Nazi party sembers were selected in the fall of 1948 and shipped to unknown destinations. Members of the SS were individually segregated during the months of January and February 1949 and removed from the camp without further information. This recently constructed camp, located on the northern edge of the city near the Bolshevik' Works, is built of stole. Medical and sanitary facilities were good by Russian standards. The fool situation was tight but prisoners were fed adequately. A small wage enabled them to supplement their diet somewhat.

Attachmenth Sketch Map of Lenin Torks, Leningrad

SECTOR SECTOR